Bridge Corrosion Monitoring System in Ogden, UT

Interim Report

Special Study S(05)07

By: Michelle Page, P.E., Program Manager Ken Berg, P.E., Development Engineer

Utah Department of Transportation Research Division

June 2005

SUMMARY

Bridge corrosion monitoring systems were installed on bridge structures in Ogden, UT by Corrosion Service Co. Ltd. The installation locations were SR-79 EB over Reeves Avenue and SR-79 WB over 31st Street. The installation detailed drawings are shown in the Appendix.

Training has been scheduled for Research Division to take the responsibility of monitoring and gathering data at the sites for the next 10 to 15 years. More information will be included in subsequent reports.